


NOTE: Mounting hardware is NOT INCLUDED with this product. Double-sided tape such as Scotch Mount™ (sold separately) or liquid adhesive such as Loctite Power Grab™ (sold separately) can be used to apply 10mm polyester acoustic panels to your wall.

Wall Surface Preparation:

- Wall surface should be clean and dry, free of oils or other contaminants. Use a lint-free cloth to dust the wall surface.
- Not for use on extremely porous wall surfaces, damp surfaces, high humidity environments, wall surfaces below 50 °F or above 100 °F, or wall surfaces with loose paint or other loose surface coatings.
- Not to be used on fine wood or delicate wall surfaces.

Application (double-sided tape - sold separately):

1. Ensure proper wall surface prep as noted above.
2. Roll out a strip of double-sided adhesive tape for the backside of each panel.
 - a. Rectangle shapes in the landscape position use two (2) strips roughly 16" long
 - b. Rectangle shapes in the portrait position use four (4) strips roughly 8" long
 - c. Square shapes use strips roughly 8" long
3. Adhere the double-sided adhesive tape to the backside of the panel as shown in the diagram above, but do not remove the film from the wall surface side. Tape should be pressed firmly by rubbing with thumb 5 or more times to attach tape well to the panel.
 
4. Once panel placement has been determined, remove the backing film from the wall surface side, avoid touching the adhesive.
5. Firmly press the panel directly to the wall mounting surface, avoid shifting once contact is made.

Application (liquid adhesive - sold separately):

1. Follow manufacturers recommendations on product
2. Apply 1/2" wide bead of liquid adhesive in a 2" circle
3. Adhesive should be at least 1" away from the panel edge. Adhesive will spread once pressed to the wall
 - a. Rectangle shapes - apply 6 circles one in each corner plus 2 in the middle of each long edge to the back of each panel
 - b. Square shapes - apply 4 circles one in each corner on the back of each panel

Place panel on the desired mounting area and apply pressure using a roller or hands. Follow adhesive label guidelines.

